

Asbestos Register

November 2025



Building Group	Building	Level	Room No. (If applicable)	Primary Location	Secondary Location	Type of Material	Application	Condition	Painted / Sealed (Yes / No)	Friable or Bonded	Inspection date	Labelling status	Sample Reference	Photo Reference Historical	Photo Reference 2025	Asbestos Yes or No	Asbestos Type (if present)	Risk Assessment	Comments	Management Plan	Laboratory No.	Analysis Certificate No.	Date Removed
A	A Block	1	-	Roof	Eave Soffits	Plasterboard	Cladding	Good	Yes	Bonded	N/A	N/A	-	A Block	N/A	No	-	-	Similar on all 3 Buildings associated with A Block	-	-	-	-
A	A Block	-	-	-	-	-	-	-	-	-	N/A	N/A	N/A	-	-	-	-	-	Rooms A-103 / A-105 / A-106 Checked H.V. Sub-Station - Not Checked - No Access	-	-	-	-
B	B Block	1	B107	Plant Room	Heater Bank in duct	Insulation	Thermal	Fair	No	Friable	N/A	N/A	S-8724	8724	N/A	No	-	-		-	OH98049/03 - 8724	COHLABS 18-3420	
B	B Block	2	B239A	Communication Room	Ceiling	Fibre-cement sheet	Cladding	Good	Yes	Bonded	N/A	N/A	S-8725	8725	N/A	No	-	-		-	OH98049/04 - 8725	COHLABS 18-3420	
B	B Block	3	B345	Communication Room	Ceiling	Fibre-cement sheet	Cladding	-	Yes	Bonded	N/A	N/A	Refer S-8725	-	N/A	No	-	-		-	-	-	
B	B Block	2	B225	Plant Room	Heater Bank in duct	Insulation	Thermal	Good	No	Friable	N/A	N/A	S-8726	8726	N/A	No	-	-		-	OH98049/05 - 8726	COHLABS 18-3420	
B	B Block	2	B208	Plant Room	Heater Bank in duct	Insulation	Thermal	Good	No	Friable	N/A	N/A	S-8727	8727	N/A	No	-	-		-	OH98049/06 - 8727	COHLABS 18-3420	
B	B Block	2	B205	Plant Room	Heater Bank in duct	Insulation	Thermal	-	-	Friable	N/A	N/A	Refer S-8727	-	N/A	No	-	-		-	-	-	
B	B Block	2	B222	Plant Room	Heater Bank in duct	Insulation	Thermal	-	-	Friable	N/A	N/A	Refer S-8727	-	N/A	No	-	-		-	-	-	
B	B Block	3	B350	Plant Room	Heater Bank in duct	Insulation	Thermal	-	-	Friable	N/A	N/A	Refer S-8727	-	N/A	No	-	-	Refer All Plant Rooms in B Block, similar Heater Bank Insulation materials	-	-	-	-
B	B Block	2	Crawl Space	Under Building	Beside Room B201	Fibre-cement sheet	Debris	Poor	No	Bonded	4/07/2025	None present	PB-47140	-	IC.01	Yes	Amosite Chrysotile	L	Restrict access without control measures in place; asbestos debris may be present throughout sub-floor; limited access	MP-4	PB-47140	-	N/A
B	B Block	3	B331	Plant Room	Heater Bank in duct	Insulation	Thermal	Good	No	Friable	N/A	N/A	S-8728	8728	N/A	No	-	-		-	OH98049/07 - 8728	COHLABS 18-3420	
B	B Block	3	B362	Ceiling Space	Framework	Fibre-cement sheet	Debris	N/A	N/A	N/A	4/07/2025	N/A	S-8729	8729 A/B	N/A	No	N	L	Inspection on 04/07/2025 revealed no asbestos debris present.	-	OH98049/08 - 8729	COHLABS 18-3420	Unknown
B	B Block	3	External	All of building	Eave Soffits	Fibre-cement sheet	Cladding	Good	Yes	Bonded	N/A	N/A	S-8730	8730 A/B	N/A	No	-	-		-	OH98049/09 - 8730	COHLABS 18-3420	
B	B Block	3	B370	Plant Room	Ceiling	Fibre-cement sheet	Cladding	Good	Yes	Bonded	N/A	N/A	S-8731	8731	N/A	No	-	-		-	OH98049/10 - 8731	COHLABS 18-3420	
B	B Block	3	B370	Plant Room	Heater Bank in duct	Insulation	Thermal	Good	No	Friable	N/A	N/A	S-8732	8732	N/A	No	-	-		-	OH98049/11 - 8732	COHLABS 18-3420	
B	B Block	3	B371	Plant Room	Heater Bank in duct	Insulation	Thermal	-	-	Friable	N/A	N/A	Refer 8732	-	N/A	No	-	-		-	-	-	
B	B Block	3	B309A	Switchroom	Ceiling	Fibre-cement sheet	Cladding	Fair	Yes	Bonded	N/A	N/A	S-8733	-	N/A	No	-	-		-	OH98049/12 - 8733	COHLABS 18-3420	
B	B Block	1	B112	External Entry	Ceiling	Fibre-cement sheet	Cladding	Good	Yes	Bonded	N/A	N/A	S-8734	8734	N/A	No	-	-		-	OH98049/13 - 8734	COHLABS 18-3420	
C	C Block	1	C115	Storeroom	Ceiling	Fibre-cement sheet	Cladding	Good	Yes	Bonded	N/A	N/A	S-8735	8735	N/A	No	-	-		-	OH98049/14 - 8735	COHLABS 18-3420	
C	C Block	1	C116	Plant Room	Heater Bank in duct	Insulation	Thermal	-	No	Friable	N/A	N/A	Refer S-8732	-	N/A	No	-	-		-	-	-	
C	C Block	1	C116	Plant Room	Ceiling	Fibre-cement sheet	Cladding	Fair	Yes	Bonded	N/A	N/A	S-8736	8736	N/A	No	-	-	Holes in ceiling	-	OH98049/15 - 8736	COHLABS 18-3420	
C	C Block	1	C112	Switchroom	Ceiling	Fibre-cement sheet	Cladding	Good	Yes	Bonded	N/A	N/A	Refer S-8736	-	N/A	No	-	-	Including Communication Room beside	-	-	-	
C	C Block	1	C110	Cleaners Room	Ceiling	Fibre-cement sheet	Cladding	Good	Yes	Bonded	N/A	N/A	Refer S-8736	-	N/A	No	-	-		-	-	-	
C	C Block	Roof	Roof Area	Above C108A	Vent Pipe	Pipe fibre-cement	Vent	Good	Yes	Bonded	4/07/2025	None present	None taken	C Block Vent Pipe	IC.02	Suspect	Suspect	L	Top section of vent pipe only, lower section is metal pipe	MP-1	-	-	N/A
C	C Block	Roof	Gables	Gable walls	Wall	Suspect ACM	Cladding	Good	Yes	Bonded	4/07/2025	None present	None taken	C Block Gable	IC.03	Suspect	Suspect	L	Rough textured walls, unable to sample	MP-1	-	-	N/A
C	C Block	1	C106	Skylight Internal	Wall	Fibre-cement sheet	Cladding	Good	Yes	Bonded	N/A	N/A	S-8737	8737 A	N/A	No	-	-		-	OH98049/16 - 8737	COHLABS 18-3420	
C	C Block	Roof	Roof Areas	Skylight External	Wall	Fibre-cement sheet	Cladding	Good	Yes	Bonded	N/A	N/A	Refer S-8737	8737 B/C	N/A	No	-	-		-	-	-	
C	C Block	1	Outside C109	Veranda ceiling	Ceiling	Fibre-cement sheet	Cladding	Good	Yes	Bonded	N/A	N/A	S-8738	8738	N/A	No	-	-		-	OH98049/17 - 8738	COHLABS 18-3420	
C	C Block	1	C108	Upper wall panels	Wall	Fibre-cement sheet	Cladding	Good	Yes	Bonded	N/A	N/A	S-8739	8739 A	N/A	No	-	-		-	OH98049/18 - 8739	COHLABS 18-3420	
C	C Block	1	C109 +	Upper wall panels	Wall	Fibre-cement sheet	Cladding	Good	Yes	Bonded	N/A	N/A	Refer S-8739	8739 B/C	N/A	No	-	-	Similar materials installed in: C104, C104A, C104G, C105, C105C	-	-	-	
C	C 1 Block	1	C1 101	Front Room	Ceiling	Fibre-cement sheet	Cladding	Good	Yes	Bonded	4/07/2025	None present	S-8722	8722	IC.04	Yes	Amosite Chrysotile	L	Front Office ceiling sample is softer than back room ceiling material (S-8723) but not Low Density Board material	MP-1	OH98049/01 - 8722	COHLABS 18-3420	N/A
C	C 1 Block	1	C1 101A	Back Room	Ceiling	Fibre-cement sheet	Cladding	Good	Yes	Bonded	4/07/2025	None present	S-8723	8723	IC.05	Yes	Chrysotile	L		MP-1	OH98049/02 - 8723	COHLABS 18-3420	N/A
D	D Block	1	D105 / D106	Dividing Wall	Panel	Fibre-cement sheet	Patch Panel	Good	Yes	Bonded	N/A	N/A	Refer S-8740	8740 B	N/A	No	-	-		-	-	-	
E	E Block	1	E107 / E108	Dividing Wall	Panel	Fibre-cement sheet	Patch Panel	Good	Yes	Bonded	N/A	N/A	S-8740	8740 A	N/A	No	-	-		-	OH98049/19 - 8740	COHLABS 18-3420	
G	G Block	1	G100A	Building Entry	Wall	Fibre-cement sheet	Cladding	Good	Yes	Bonded	N/A	N/A	S-8741	8741 A/B	N/A	No	-	-		-	OH98049/20 - 8741	COHLABS 18-3420	

Building Group	Building	Level	Room No. (If applicable)	Primary Location	Secondary Location	Type of Material	Application	Condition	Painted / Sealed (Yes / No)	Friable or Bonded	Inspection date	Labelling status	Sample Reference	Photo Reference Historical	Photo Reference 2025	Asbestos Yes or No	Asbestos Type (if present)	Risk Assessment	Comments	Management Plan	Laboratory No.	Analysis Certificate No.	Date Removed
G	G Block	Roof	Above G101	Vertical walls	Wall	Fibre-cement sheet	Cladding	Good	Yes	Bonded	N/A	N/A	Refer S-8741	8741 C	N/A	No	-	-		-	-	-	
G	G Block	1	G100A	Building Entry	Ceiling	Fibre-cement sheet	Cladding	Good	Yes	Bonded	N/A	N/A	S-8742	8742	N/A	No	-	-		-	OH98049/21 - 8742	COHLABS 18-3420	
G	G Block	1	Rear of Building	Roof	Eave Soffits	Fibre-cement sheet	Cladding	Fair	Yes	Bonded	N/A	N/A	S-8743	8743 A	N/A	No	-	-	Some damage	-	OH98049/22 - 8743	COHLABS 18-3420	
G	G Block	1	G103	Infill Panel	Panel	Fibre-cement sheet	Cladding	Good	Yes	Bonded	N/A	N/A	Refer S-8743	8743 B	N/A	No	-	-		-	-	-	
G	G Block	1	G103	Condenser Room	Ceiling	Fibre-cement sheet	Cladding	Good	Yes	Bonded	N/A	N/A	Refer S-8743	-	N/A	No	-	-		-	-	-	
G	G Block	1	External G112A	Veranda	Floor	Compressed cement sheet	Flooring	Fair	No	Bonded	N/A	N/A	S-8744	8744	N/A	No	-	-		-	OH98049/23 - 8744	COHLABS 18-3420	
G	G Block	1	External G112A	Wall Panels	Wall	Compressed cement sheet	Cladding	Good	Yes	Bonded	N/A	N/A	S-8745	8745	N/A	No	-	-		-	OH98049/24 - 8745	COHLABS 18-3420	
G	G Block	1	G112	Gymnasium	Ceiling	Fibre-cement sheet	Cladding	Good	Yes	Bonded	N/A	N/A	S-8746	8746	N/A	No	-	-		-	OH98049/25 - 8746	COHLABS 18-3420	
G	G 1	-	Tennis Court Shelter	-	-	-	-	N/A	N/A	-	-	-	-	G 1	-	-	-	-	Metal construction	-	-	-	
H	H Block	1	H119	Plant Room	Wall	Fibre-cement sheet	Cladding	Good	Yes	Bonded	N/A	N/A	S-8747	8747	N/A	No	-	-		-	OH98049/26 - 8747	COHLABS 18-3420	
H	H Block	1	Level 1	Rooms	Wall	Fibre-cement sheet	Cladding	Good	Yes	Bonded	N/A	N/A	Refer S-8747	-	N/A	No	-	-	Material used throughout this level	-	-	-	
H	H Block	2	External	Veranda	Ceiling	Fibre-cement sheet	Cladding	Good	Yes	Bonded	N/A	N/A	S-8748	8748 A	N/A	No	-	-	Some damage observed	-	OH98049/27 - 8748	COHLABS 18-3420	
H	H Block	2 & 3	External	Veranda / Eave Soffits	Ceiling	Fibre-cement sheet	Cladding	Good	Yes	Bonded	N/A	N/A	Refer S-8748	8748 B	N/A	No	-	-		-	-	-	
H	H Block	2	Foyer	Service Room	Wall	Fibre-cement sheet	Cladding	Good	Yes	Bonded	N/A	N/A	S-8749	8749	N/A	No	-	-	Beside Laboratory / Lecture Room	-	OH98049/28 - 8749	COHLABS 18-3420	
I	I Block	3	External	Eave Soffits	Ceiling	Fibre-cement sheet	Cladding	Good	Yes	Bonded	N/A	N/A	Refer 8748	I Block	N/A	No	-	-		-	-	-	
J	J Block	-	External	Eave Soffits	Ceiling	Fibre-cement sheet	Cladding	Good	Yes	Bonded	N/A	N/A	Refer 8748	J Block	N/A	No	-	-		-	-	-	
P	P Block	1	P102	Plant Room	Heater Bank in duct	Insulation	Thermal	Good	No	Friable	N/A	N/A	S-8750	8750	N/A	No	-	-		-	OH98049/29 - 8750	COHLABS 18-3420	
P	P Block	1	External	Veranda	Ceiling	Fibre-cement sheet	Cladding	Fair	Yes	Bonded	N/A	N/A	S-8751	8751	N/A	No	-	-		-	OH98049/30 - 8751	COHLABS 18-3420	
P	P Block	2	External	Veranda	Ceiling	Fibre-cement sheet	Cladding	Good	Yes	Bonded	N/A	N/A	Refer S-8751	-	N/A	No	-	-		-	-	-	
M	M Block	1	External	Veranda	Ceiling	Fibre-cement sheet	Cladding	Good	Yes	Bonded	N/A	N/A	S-8752	8752	N/A	No	-	-		-	OH98049/31 - 8752	COHLABS 18-3420	
M	M Block	1	External	Eave Soffits	Ceiling	Fibre-cement sheet	Cladding	Good	Yes	Bonded	N/A	N/A	Refer S-8752	8752	N/A	No	-	-	Narrow Eave, one side of building only	-	-	-	
M	M Block	1	M103	Plant Room	Heater Bank in duct	Insulation	Thermal	-	No	Friable	N/A	N/A	Refer S-8750	-	N/A	No	-	-		-	-	-	
M	M Block	1	Walk Through	Hall	Ceiling	Fibre-cement sheet	Cladding	Good	Yes	Bonded	N/A	N/A	S-8753	8753	N/A	No	-	-		-	OH98049/32 - 8753	COHLABS 18-3420	
R	R Block	1	External	Fire Hose Reel Cabinet	Ceiling	Fibre-cement sheet	Cladding	Good	Yes	Bonded	N/A	N/A	S-8754	8754	N/A	No	-	-		-	OH98049/33 - 8754	COHLABS 18-3420	
R	R Block	2	R201	Plant Room	Heater Bank in duct	Insulation	Thermal	-	No	Friable	N/A	N/A	Refer S-8750	-	N/A	No	-	-	Not Able to Access	-	-	-	
S	S Block	-	-	Plant Room	Heater Bank in duct	Insulation	Thermal	-	No	Friable	N/A	N/A	Refer S-8750	-	N/A	No	-	-	Not Able to Access	-	-	-	
Y	Y Block	1	All Rooms	Rooms	Ceiling	Fibre-cement sheet	Cladding	Good	Yes	Bonded	2/07/2025	None present	S-8755	8755 A/B	IC.44; IC.45	Yes	Chrysotile	L	Paint Peeling; generally deteriorated	MP-2	OH98049/34 - 8755	COHLABS 18-3420	
Y	Y Block	1	Kitchen	Cabinets	Shelf Lining	Asbestos backed vinyl sheeting	Shelf lining	Poor	No	Friable	2/07/2025	None present	Q45770S05	-	IC.46	Yes	Chrysotile	L	Friable material in poor condition; removal recommended	MP-5	Q45770S05	Q45770R01	
Q	Q Block	1	Q117	Boiler	Flanges	Gaskets	Installed	Good	No	Bonded	4/07/2025	None present	PB-2993	Boiler	IC.06; IC.07	Yes	Chrysotile	L	Refer to previous report for sample No. PB-2993 Items not accessed 2018 or 2025 Inspection	MP-5	PB-2993	-	N/A
O	O Block	1	O106	Plant Room	Heater Bank in duct	Insulation	Thermal	-	No	Friable	N/A	N/A	S-8756	8756	N/A	No	-	-		-	OH98049/35 - 8756	COHLABS 18-3420	
O	O Block	2	O202 / O203	Rooms	Ceiling	Fibre-cement sheet	Cladding	Good	Yes	Bonded	4/07/2025	None present	-	O Block	IC.08; IC.09	Suspect	Suspect	L	Unable to access due to height restrictions.	MP-1	-	-	N/A
N	N Block	-	No Samples Collected	-	-	-	-	N/A	N/A	-	-	-	-	-	-	-	-	-	Inspection revealed no suspected asbestos containing materials.	-	-	-	
K	K Block	1	K199	Foyer	Wall	Fibre-cement sheet	Cladding	Good	Yes	Bonded	N/A	N/A	S-8757	8757 A/B	N/A	No	-	-	Entry walls to rooms K102 / K105	-	OH98049/36 - 8757	COHLABS 18-3420	
L	L Block	1	L108 / L109	Service Room	Internal divider wall	Fibre-cement sheet	Cladding	Good	No	Bonded	N/A	N/A	S-8758	8758	N/A	No	-	-		-	OH98049/37 - 8758	COHLABS 18-3420	
L	L Block	1	L108 / L109	Service Room	External walls	Fibre-cement sheet	Cladding	Good	Yes	Bonded	N/A	N/A	S-8759	8759	N/A	No	-	-		-	OH98049/38 - 8759	COHLABS 18-3420	
L	L Block	1	L117	Outdoor Dining	Ceiling	Fibre-cement sheet	Cladding	Good	Yes	Bonded	N/A	N/A	S-8760	8760	N/A	No	-	-		-	OH98049/39 - 8760	COHLABS 18-3420	

Building Group	Building	Level	Room No. (If applicable)	Primary Location	Secondary Location	Type of Material	Application	Condition	Painted / Sealed (Yes / No)	Friable or Bonded	Inspection date	Labelling status	Sample Reference	Photo Reference Historical	Photo Reference 2025	Asbestos Yes or No	Asbestos Type (if present)	Risk Assessment	Comments	Management Plan	Laboratory No.	Analysis Certificate No.	Date Removed
L	L Block	1	L104	Canteen, Ceiling access	Cover	Fibre-cement sheet	Panel	Good	Yes	Bonded	N/A	N/A	S-8761	8761	N/A	No	-	-	1 access cover, near exit door for Canteen Kitchen Remainder of access covers & ceilings are plasterboard	-	OH98049/40 - 8761	COHLABS 18-3420	
L	L Block	1	L103	Cash Register	Wall	Fibre-cement sheet	Cladding	Good	Yes	Bonded	N/A	N/A	S-8762	8762	N/A	No	-	-		-	OH98049/41 - 8762	COHLABS 18-3420	
L	L Block	1	External	Soffits	Ceiling	Fibre-cement sheet	Cladding	N/A	N/A	-	4/07/2025	N/A	PB-59863	-	IC.10	No	N/A	-	No fibre cement soffit lining present; new awning in place	-	PB-59863	-	Unknown
L	L Block	2	L202	Plant Room	Heater Bank in duct	Insulation	Thermal	-	-	-	4/07/2025	N/A	-	-	IC.11	No	N/A	-	Inspection revealed modern heater bank with no suspected asbestos containing materials.	-	-	-	
U	U Block	1	All Rooms	Room	Ceiling	Fibre-cement sheet	Cladding	Good	Yes	Bonded	N/A	N/A	S-8763	8763 A/B	N/A	No	-	-		-	OH98049/42 - 8763		
X	X Block	1	X106	Room	Debris on timber studs	Fibre-cement sheet	Debris	Poor	No	Bonded	2/07/2025	None present	PB-31282	-	IC.12; IC.13	Yes	Chrysotile	L	Not Accessed; Installed to studs throughout, previous report information	MP-4	PB-31282	-	
X	X Block	1	X114	Room	Debris on timber studs	Fibre-cement sheet	Debris	Poor	No	Bonded	2/07/2025	N/A	PB-31281	-		No	N/A		Inspection of the room in 2025 revealed no asbestos cement sheeting residues to be present on timber framing.		PB-31281	-	Unknown
X	X Block	Roof	Roof Area	Various	Vent Pipe	Pipe fibre-cement	Vent	Fair	Yes	Bonded	2/07/2025	None present	-	Vent Pipes A/B	IC.13; IC.15; IC.16; IC.17; IC.18	Suspect	Suspect	L	Top section of vent pipes only, lower sections are metal pipe	MP-1	-	-	
X	X Block	1	N/A	External south	Drain trap	Fibre-cement sheet	Plumbing drain trap surround formwork	Fair	No	Bonded	2/07/2025	None present	Q45770S01		IC.19	Yes	Amosite Chrysotile	L	Currently unpainted; coating recommended	MP-2	Q45770S01	Q45770R01	
W	W Block	1	W102	Rooms	Floor Tiles	Vinyl Tiles	Flooring	Fair	Yes	Bonded	2/07/2025	None present	PB-31274	Floors A/B	IC.30	Yes	Chrysotile	L	Tiles generally stable with areas of damage and deterioration present .	MP-4	PB-31274	-	
W	W Block	1	W102	Rooms	Adhesive for floor tiles	Glue	Adhesive	Fair	Yes	Bonded	2/07/2025	None present	PB-31277	-		Yes	Chrysotile	L	Mastic adhesive generally stable and covered by tiles.	MP-4	PB-31277	-	
W	W Block	1	W103A	Room	Floor Tiles	Vinyl Tiles	Flooring	Fair	Yes	Bonded	2/07/2025	None present	PB-31280	-	IC.29	Yes	Chrysotile	L	Tiles generally stable with areas of damage and deterioration present .	MP-4	PB-31280	-	
W	W Block	1	W103A	Room	Adhesive for floor tiles	Glue	Adhesive	Fair	Yes	Bonded	2/07/2025	None present	Refer PB-31277	-		Yes	Chrysotile	L	Mastic adhesive generally stable and covered by tiles.	MP-4	-	-	
W	W Block	1	W106	Rooms	Floor Tiles	Vinyl Tiles	Flooring	Fair	Yes	Bonded	2/07/2025	None present	PB-31274	Floors A/B	IC.20; IC.21	Yes	Chrysotile	L	Tiles generally stable with areas of damage and deterioration present .	MP-4	PB-31274	-	
W	W Block	1	W106	Rooms	Adhesive for floor tiles	Glue	Adhesive	Fair	Yes	Bonded	2/07/2025	None present	PB-31277	-	IC.20	Yes	Chrysotile	L	Mastic adhesive generally stable and covered by tiles.	MP-4	PB-31277	-	
W	W Block	1	W109	Room	Floor Tiles	Vinyl Tiles	Flooring	Fair	Yes	Bonded	2/07/2025	None present	PB-31280	-	IC.20; IC.21	Yes	Chrysotile	L	Tiles generally stable with areas of damage and deterioration present .	MP-4	PB-31280	-	
W	W Block	1	W109	Room	Adhesive for floor tiles	Glue	Adhesive	Fair	Yes	Bonded	2/07/2025	None present	Refer PB-31277	-	IC.20	Yes	Chrysotile	L	Mastic adhesive generally stable and covered by tiles.	MP-4	-	-	
W	W Block	1	W115	Rooms	Floor Tiles	Vinyl Tiles	Flooring	Fair	Yes	Bonded	2/07/2025	None present	PB-31274	Floors A/B	IC.23	Yes	Chrysotile	L	Tiles generally stable with areas of damage and deterioration present .	MP-4	PB-31274	-	
W	W Block	1	W115	Rooms	Adhesive for floor tiles	Glue	Adhesive	Fair	Yes	Bonded	2/07/2025	None present	PB-31277	-		Yes	Chrysotile	L	Mastic adhesive generally stable and covered by tiles.	MP-4	PB-31277	-	
W	W Block	1	W118	Room	Floor Tiles	Vinyl Tiles	Flooring	Fair	Yes	Bonded	2/07/2025	None present	PB-31280	-		Yes	Chrysotile	L	Tiles generally stable with areas of damage and deterioration present .	MP-4	PB-31280	-	
W	W Block	1	W118	Room	Adhesive for floor tiles	Glue	Adhesive	Fair	Yes	Bonded	2/07/2025	None present	Refer PB-31277	-	IC.22	Yes	Chrysotile	L	Mastic adhesive generally stable and covered by tiles.	MP-4	-	-	
W	W Block	1	W123	Rooms	Floor Tiles	Vinyl Tiles	Flooring	Fair	Yes	Bonded	2/07/2025	None present	PB-31274	Floors A/B	IC.26	Yes	Chrysotile	L	Tiles generally stable with areas of damage and deterioration present .	MP-4	PB-31274	-	
W	W Block	1	W123	Rooms	Adhesive for floor tiles	Glue	Adhesive	Fair	Yes	Bonded	2/07/2025	None present	PB-31277	-		Yes	Chrysotile	L	Mastic adhesive generally stable and covered by tiles.	MP-4	PB-31277	-	
W	W Block	1	W124	Room	Floor Tiles	Vinyl Tiles	Flooring	Fair	Yes	Bonded	2/07/2025	None present	PB-31280	-	IC.27	Yes	Chrysotile	L	Tiles generally stable with areas of damage and deterioration present .	MP-4	PB-31280	-	
W	W Block	1	W124	Room	Adhesive for floor tiles	Glue	Adhesive	Fair	Yes	Bonded	2/07/2025	None present	Refer PB-31277	-		Yes	Chrysotile	L	Mastic adhesive generally stable and covered by tiles.	MP-4	-	-	
W	W Block	1	W125	Room	Floor Tiles	Vinyl Tiles	Flooring	Fair	Yes	Bonded	2/07/2025	None present	PB-31280	-	IC.28	Yes	Chrysotile	L	Tiles generally stable with areas of damage and deterioration present .	MP-4	PB-31280	-	
W	W Block	1	W125	Room	Adhesive for floor tiles	Glue	Adhesive	Fair	Yes	Bonded	2/07/2025	None present	Refer PB-31277	-		Yes	Chrysotile	L	Mastic adhesive generally stable and covered by tiles.	MP-4	-	-	
W	W Block	1	W126	Rooms	Floor Tiles	Vinyl Tiles	Flooring	Fair	Yes	Bonded	2/07/2025	None present	PB-31274	Floors A/B	IC.24	Yes	Chrysotile	L	Tiles generally stable with areas of damage and deterioration present .	MP-4	PB-31274	-	
W	W Block	1	W126	Rooms	Adhesive for floor tiles	Glue	Adhesive	Fair	Yes	Bonded	2/07/2025	None present	PB-31277	-		Yes	Chrysotile	L	Mastic adhesive generally stable and covered by tiles.	MP-4	PB-31277	-	
W	W Block	1	W127	Room	Floor Tiles	Vinyl Tiles	Flooring	Fair	Yes	Bonded	2/07/2025	None present	PB-31280	-	IC.31	Yes	Chrysotile	L	Tiles generally stable with areas of damage and deterioration present .	MP-4	PB-31280	-	
W	W Block	1	W127	Room	Adhesive for floor tiles	Glue	Adhesive	Fair	Yes	Bonded	2/07/2025	None present	Refer PB-31277	-		Yes	Chrysotile	L	Mastic adhesive generally stable and covered by tiles.	MP-4	-	-	
W	W Block	1	W198A	Room	Floor Tiles	Vinyl Tiles	Flooring	Fair	Yes	Bonded	2/07/2025	None present	Q45770S04	-		Yes	Chrysotile	L	Tiles generally stable with areas of damage and deterioration present .	MP-4	PB-31280	-	
W	W Block	1	W107	Room	Floor Tiles	Vinyl Tiles	Flooring	Fair	Yes	Bonded	2/07/2025	None present	Q45770S04	-		Yes	Chrysotile	L	Tiles generally stable with areas of damage and deterioration present .	MP-4	PB-31280	-	
W	W Block	1	W108	Room	Floor Tiles	Vinyl Tiles	Flooring	Fair	Yes	Bonded	2/07/2025	None present	Q45770S04	-		Yes	Chrysotile	L	Tiles generally stable with areas of damage and deterioration present .	MP-4	PB-31280	-	
W	W Block	1	W112	Room	Floor Tiles	Vinyl Tiles	Flooring	Fair	Yes	Bonded	2/07/2025	None present	Q45770S04	-	IC.25	Yes	Chrysotile	L	Tiles generally stable with areas of damage and deterioration present .	MP-4	PB-31280	-	
W	W Block	1	Entry Annexe	Room	Wall	Fibre-cement sheet	Cladding	Good	Yes	Bonded	2/07/2025	None present	PB-31272	-	IC.33; IC.34	Yes	Chrysotile	L	Southern, Eastern & Western walls	MP-1	PB-31272	-	

